

Construction | Environmental | Compliance

## Work Experience: DC Inspector License

	(A) Address	(B) Activity	(C) Date of Activity		
1,2,3	300 Bryant St NW Washington DC 20001	Paint chip sampling & XRF	6/10/25, 6/12/25, 7/30/25		
(D)	Performed LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
4	504-B Van Dorn Street Alexandria, VA 22304	XRF	8/29/25		
(D)	Performed LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
5	1900 Gallaudet Street NW Washington DC 20002	Paint chip sampling & XRF	6/5/25		
(D)	Performed LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
6	6014 Sligo Mill Rd NE, DC, 20011	XRF	5/22/25		
(D)	Performed LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
7	11800 Nebel Street Rockville, MD 20852	XRF	4/11/25		
(D)	Performed LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
8	1001 G St SE, Washington, DC 20003	XRF	6/17/25		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
9	5701 Broad Branch Rd NW, Washington, DC 20015	XRF	6/13/25		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				



Construction | Environmental | Compliance

10	1555 34th St NW, Washington, DC	YDE	6/2/25		
10	20007	Alti	0/2/23		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
11	1625 P St NW, Washington, DC 20036	XRF	6/2/25		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
12	1730 R St NW, Washington, DC 20009	XRF	6/2/25		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
13	3219 O St NW, Washington, DC 20007	XRF	6/2/25		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
14	920 F St NE, Washington, DC 20002	XRF	5/2/25		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
	659 G St NE, Washington, DC 20002	XRF	5/2/25		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
16	640 10 <sup>th</sup> Street NE Washington DC 20002	XRF	4/28/25		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
17	3 <sup>rd</sup> & L Street NE	XRF	4/28/25		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				



Construction | Environmental | Compliance

18	1125 New Jersey Ave NW, Washington, DC 20001	XRF	4/28/25		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
19	501 Riggs Rd NE Washington DC 20011	XRF	4/22/25		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				
20	101 T St NE, Washington, DC 20002	XRF	4/22/25		
(D)	Performed limited LBP survey at the address. Assisted in the performance of Lead Based Paint survey. Assisted with the documentation, site walk-through, and reporting.				

Supervisor/Manager confirming that based on the work performed at the listed addresses the applicant is knowledgeable about and capable of conducting lead- based paint inspections and adhering to federal, state and local regulations.

Lian Zadeng lzadeng@atmossolutionsinc.com (240) 620-7424